

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 15-12-2021		District: Arany
Division : R.W.D. Arany		Length (km): 1.88 km
Name of the Road: Eilabar Chowk To Gilbari Mahakalit tols		
Scheme/Programme: MMBGY (SC)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT 4 C.C.	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- BT Surface is rough & Pot developed in ch. 150 to 200 m, 250 to 300 m. C.C. Surface is satisfactory. Maintenance work in progress.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
d)	Condition of Vent Clearance	S
Observation Remarks:- H.P. culvert is in good condition.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained.	
Observation Remarks:- Road furniture; Informatory Board & Maintenance Board K.M. Post & 200 M Post is fixed in road.		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

Designature:-

AE
15-12-21
AE

15-12-2021
(Signature)
E.E