

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 14-12-2021		District: Araria
Division : R.W.D. Araria		Length (km): 2.469 Km
Name of the Road: Laluvabani P.M.G. Sy Near Bridge to Burnea Sime via Karkhama		
Scheme/Programme: MMGSY (ST)		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B.T 4 C.C	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- B.T surface is rough due to over top of flood water ch. of 60 m, SW to NW. Maintenance work in progress. C.C. surface is satisfactory.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S
Observation Remarks:- R.C.C. culvert is in good condition		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	
Observation Remarks:- Road furniture; Informatory & Maintenance Board, K.M Post and 200 M Post is fixed in road		
4.	Compliance History	
a)	Status of ATR's & any others	—


Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

Designature:-


 14-12-21
 AB


 14-12-2021
 (Signature)
 E-G