

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 14-12-2021		District: Aranyg	
Division : R.W.D Aranyg		Length (km): 2.50 km	
Name of the Road: Baiygaahi Mahalgawan P.M. 659 Dumaria To Akona Tola			
Scheme/Programme:		NABARD	
Sl. No.	Parameters to be checked		Remarks (S/U)
1.	Pavement B.T 4 CC		
a)	Condition of Surfacing		S
b)	Riding Quality		S
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S
e)	Contraction Joints provided or not (CC Pavement)		S
f)	Compaction of flank/slope & raincuts if any		S
Observation Remarks:- Road surface is in good condition			
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S
c)	Condition of railings/slab/approach for Bridges		S
d)	Condition of Vent Clearance		S
Observation Remarks:- R.C.C culvert is in good condition			
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained		S
Observation Remarks:- Road Furniture ; Informatory Board & Maintenance Board, K.M. & 200m Post is fixed in road.			
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-
Designature:-

ABW
14-12-2021

u/s
14-12-2021
(Signature)
E.E.