

INSPECTION REPORT FOR ROUTINE MAINTENANCE

22

Date of Inspection : 13/12/2021 District: Vaishali
 Division : Hargpur Length (km): 1.731
 Name of the Road: Simra PMGSY Road to Pulsar South Tola
 Scheme/Programme: MMGSY(SC)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U &

Observation Remarks:-

B.T. NA.
 Flank not completed due to private land.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

13/3
 13/12/2021

Sub
 13/12/21
 A.E.