

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 13/12/21

District: Subaul

Division: VITPAR

Length (km): 3.25

Name of the Road: Repair of Road from Karjason Bazar to Vayesi
Kali Mandir

Scheme/Programme:

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 100m stones/Pavement road markings are provided and maintained	U

Observation Remarks:- Road furniture not maintained

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating Unsatisfactory

(Signature)
13/12/21
A.E.
(Ramesh Chandra)

(Signature)
13/12/21
E.E.
Reg. Lab. Darbhanga