

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 14-12-2021	District: Aranyig
Division : R.W.D Aranyig	Length (km): 13.90 km.
Name of the Road: Dokhat to Simanyig Path	
Scheme/Programme: MR	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
e)	Contraction Joints provided or not (CC Pavement)	NA
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

Road surface is in good condition

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S

Observation Remarks:-

H.D. & R.C.C culvert is in good condition

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:- Road Furniture i.e. Informatory & Maintenance Board, km post & 200m post is fixed in road

4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

Designature:-

ABD
14-12-2021
AB

22/12/2021
14-12-2021
(Signature)
E-E