

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

|                                              |                      |
|----------------------------------------------|----------------------|
| Date of Inspection : 14.12.2021              | District: Aranyas    |
| Division : R.W.D Aranyas                     | Length (km): 9.12 KM |
| Name of the Road: Bhansing to Bainsda Part 4 |                      |
| Scheme/Programme: MR                         |                      |

| Sl. No. | Parameters to be checked                                                                     | Remarks (S/U) |
|---------|----------------------------------------------------------------------------------------------|---------------|
| 1.      | <b>Pavement</b> B.T                                                                          |               |
| a)      | Condition of Surfacing                                                                       | U             |
| b)      | Riding Quality                                                                               | U             |
| c)      | Road Camber                                                                                  | S             |
| d)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | N.A           |
| e)      | Contraction Joints provided or not (CC Pavement)                                             | N.A           |
| f)      | Compaction of flank/slope & raincuts if any                                                  | S             |

**Observation Remarks:-** B.T surface is rough due to flow water over top. for ch. 20 M to 250 + 350 to 400 M. Maintenance work is in progress

|    |                                                                      |   |
|----|----------------------------------------------------------------------|---|
| 2. | <b>Cross Drainage</b>                                                |   |
| a) | Condition of head walls in Hume pipe culverts including its painting | S |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts             | S |
| c) | Condition of railings/slab/approach for Bridges                      | S |
| d) | Condition of Vent Clearance                                          | S |

**Observation Remarks:-** H.W. & R.C.C culvert is in good condition


|    |                                                                                                                       |   |
|----|-----------------------------------------------------------------------------------------------------------------------|---|
| 3. | <b>Road Furniture</b>                                                                                                 |   |
| a) | Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained | S |


**Observation Remarks:-** Road Furniture, Informatory Board, Maintenance Board, KM Post 4.200 M post is fixed in place

|    |                              |  |
|----|------------------------------|--|
| 4. | <b>Compliance History</b>    |  |
| a) | Status of ATR's & any others |  |

|                  |                                      |   |
|------------------|--------------------------------------|---|
| Overall Rating : | Satisfactory (S)/ Unsatisfactory (U) | U |
|------------------|--------------------------------------|---|

Name of Officer:-  
Designature:-

  
 (Signature) 14.12.2021  
 E.E

  
 14.12.2021  
 A.B