

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 14/12/2021 District: Supaul
 Division : Nixpur Length (km): 1.055
 Name of the Road: House of Kailu Lam Hlab 397
 Scheme/Programme: CTSNY

Sl. No.	Parameters to be checked	Remarks (S/N)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory

14/12/21
 AE
 (Rameshwar prasad)

14/12/21
 Executive Engineer
 RWD Regional Laboratory
 Darbhanga