

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 15-12-2021		District: Aranyga
Division : R.W.D. Aranyga		Length (km): 0.256 km
Name of the Road: Kullahayat Salehat School to House of Kuddas		
Scheme/Programme: G.T.S.N.Y.		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
<b>Observation Remarks:-</b> Road surface is in good condition		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	N.A
<b>Observation Remarks:-</b> N.A		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	
<b>Observation Remarks:-</b> Road furniture; Informatory & Maintenance Board, K.M. Post & 200m Post is fixed in road.		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

Designature:-

15-12-2021  
 (Signature)  
 E-E

15-12-21  
 AE