

INSPECTION REPORT FOR ROUTINE MAINTENANCE

19

Date of Inspection : 15/12/2021 District: Vaishali
 Division : Hagiapur Length (km): 1.7
 Name of the Road: Laxmi Narayan Mahavidyalay NH-77 Bhagwanpur
 Scheme/Programme: PMGSY-NEA. (New MR)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

C.C.P. NA.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

15/12/2021

SMA
15/12/21
A.E