

INSPECTION REPORT FOR ROUTINE MAINTENANCE

23

Date of Inspection : 11/12/2021	District: Vaishali
Division : Hagi pur	Length (km): 1.61
Name of the Road: Lalganj vaishali road ke petrol pump ke utty gram bataraul hanjan tota basti hotelue to PMGSY lakshminarayanpur road tak.	
Scheme/Programme: MMBSY (SC)	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

some BT portion damaged due to flood.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	-

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ kur & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

1393
11/12/2021
E.E

S.S.
11/12/21
A.E.