

INSPECTION REPORT FOR ROUTINE MAINTENANCE

16

Date of Inspection : 11/12/2021 District: Vaishali
 Division : Hagi pur Length (km): ~~NABARD~~ 2.10 km.
 Name of the Road: Lalgang hagi pur road to dhanushi gram Uday Singh House
 to dhanushi vishu Kumar Ke boring tak
 Scheme/Programme: NABARD.

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	-
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

Some parts BT damaged due to flood.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 300m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

3/2
11/12/2021

S/2
11/12/21
A.E.