

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 17/12/2021	District: Vaishali
Division : Hagi pur	Length (km): 2.0
Name of the Road: Totha to Sehulapur	
Scheme/Programme: MR	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	-
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	-
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

Some parts (PCC part) flank not complete due to private land.
B.T. damaged some portion due to flood.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	-

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 100m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) U

Name of Officer:-

MB
17/12/2021
E-E

SA
17/12/21
A.E.