

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 17.12.2021		District: Kabhar
Division : Baran		Length (km): 1.150
Name of the Road: Shadipur Litchi Bagan to Bengol Sima tak via Gossipur		
Scheme/Programme: NABARD		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any <i>no rain cuts.</i>	S
Observation Remarks:- <i>Surface condition is satisfactory and there is no rain cuts in flank.</i>		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- *Rana Basun Kumar Singh*
 Designature:- *Executive Engineer, Regional Lab. Bhagalpur.*

17.12.2021
 (Signature)