

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 18.12.2021		District: Katihar
Division : Barh		Length (km): 3.100
Name of the Road: L049 - Siporna to Khushalpur		
Scheme/Programme: PMGSY		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
e)	Contraction Joints provided or not (CC Pavement)	N.A
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- Surface damaged due to flood water in approximately 1850 meter length of this road. This road is between Mahamunda river and the Barh so that flooded water frequently occur.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:- —		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Unsatisfactory (U)

Name of Officer: Rana Broom Kumar Singh

Designature: Executive Engineer, Regional Lab. Bhagalpur.


 18.12.2021
 (Signature)