

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 17.12.2021	District: Kothari
Division : Baran	Length (km): 2.918
Name of the Road: LOSI - TOI Kurnu to Mehinagar.	
Scheme/Programme:	PMBSY

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
e)	Contraction Joints provided or not (CC Pavement)	N.A
f)	Compaction of flank/slope & raincuts if any NO rain cuts	S

Observation Remarks:- Surface condition is satisfactory. Last 30m (approx.) length of the road is plough into Mehavanda river.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Rana Bhoon Kumar Singh
 Designature:- Executive Engineer, Regional Lab. Bhopal

17.12.2021
 (Signature)