

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 16.12.2021

District : Katihar

Division : Bara

Length (km) : 2.323

Name of the Road : Block Head Quarter Kumhari to Mahadalitola via Brahmanpola, Saitola

Scheme/Programme : MMHSY(SC)

| Sl. No. | Parameters to be checked                                                                     | Remarks (S/U) |
|---------|----------------------------------------------------------------------------------------------|---------------|
| 1.      | <b>Pavement</b>                                                                              |               |
| a)      | Condition of Surfacing                                                                       | S             |
| b)      | Riding Quality                                                                               | S             |
| c)      | Road Camber                                                                                  | S             |
| d)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | S             |
| e)      | Contraction Joints provided or not (CC Pavement)                                             | S             |
| f)      | Compaction of flank/slope & raincuts if any                                                  | S             |

Observation Remarks:- Surface Condition is Satisfactory.

|    |                                                                      |   |
|----|----------------------------------------------------------------------|---|
| 2. | <b>Cross Drainage</b>                                                |   |
| a) | Condition of head walls in Hume pipe culverts including its painting | S |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts             | — |
| c) | Condition of railings/slab/approach for Bridges                      | — |
| d) | Condition of Vent Clearance                                          | S |

Observation Remarks:-

|    |                                                                                                                       |   |
|----|-----------------------------------------------------------------------------------------------------------------------|---|
| 3. | <b>Road Furniture</b>                                                                                                 |   |
| a) | Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained | S |

Observation Remarks:-

|    |                              |   |
|----|------------------------------|---|
| 4. | <b>Compliance History</b>    |   |
| a) | Status of ATR's & any others | — |

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- Rana Basim Kumar Singh

Designature:- Executive Engineer, Regional Lab. Bhagalpur.

16.12.2021  
(Signature)