

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 15.12.2021		District: Katihar
Division : Barauni		Length (km): 8.250
Name of the Road: Repair of Road from Kajitola to Barigol via Shivrandpur		
Scheme/Programme: MR-3054		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
e)	Contraction Joints provided or not (CC Pavement)	N.A
f)	Compaction of flank/slope & raincuts if any <i>no rain cuts.</i>	S
Observation Remarks:- <i>Surface Condition is Satisfactory.</i>		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (S)

Name of Officer:- *Rana Basim Kumar Singh*

Designature:- *Executive Engineer, Regional Lab. Bhagalpur.*

15.12.2021
(Signature)