INSPECTION REPORT FOR ROUTINE MAINTENANCE

. ja

| | INSPECTION REPORT FOR R | OUTINE MAINTENANCE | |
|--|---|--|------------------|
| Date of Inspection: 15/12/2021 District: Auranga bad | | | |
| | | | å _v , |
| Name of the Road: TOG, Deo Road to Karmadeh | | | 75.4.7 |
| | e/Programme: CoTSNY | Olea Print Line version en la villa de l'IVIII | 4,11 |
| Sl. No. | Parameters to be che | cked | Remarks (S/U) |
| 1. | Pavement | | |
| a) | Condition of Surfacing | | U |
| b) | Riding Quality | | U. |
| c) | Road Camber | | 5 |
| d) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | U. |
| e) | Contraction Joints provided or not (CC Pay | rement) | S |
| f) | Compaction of flank/slope & raincuts if any | | U . |
| Observation Remarks:- | | | |
| Maintenance wask was going on | | | to a same |
| 0 0 | |) () | |
| | | | 0 00 70 |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | S |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | |
| c) | Condition of railings/slab/approach for Bridges | | - |
| d) [| Condition of Vent Clearance | | S |
| Observation Remarks:- | | | |
| manitained | | | A sq |
| | | | 10 T |
| | | | TO THE |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained | | V · |
| Observation Remarks:- | | | - |
| Maintenance work was going on. | | | W. 1896 |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | | |
| Oxen-11 | Dodina | | Total |
| Overall | Satisfactory (S)/ Un | satisfactory (U) | 1 1 |

Name of Officer: Kymar Rakesh

Designature:-

(Signature)