INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 15/12/2021 District: Auranga bad		**	
Division: Hurangabae Length (km): 0.75 km			Ξψ
Name of the Road: Loy3 to Anjaniya			16.4.4
Scheme/Programme: PMGSY			* 49.4
Sl. No.	Parameters to b	e checked	Remarks (S/U)
1.	Pavement		
a)	Condition of Surfacing		V.
b)	Riding Quality		· Uzzz
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		V.
e)	Contraction Joints provided or not (CC Pavement)		5_
f)	Compaction of flank/slope & raincuts if any		V
Observation Remarks:-			
Road mot maintained			814 X-4
			Table 1
			9572" 12 104
2.	Cross Drainage	500	
a)	Condition of head walls in Hume pipe culverts including its painting		U The same of the
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S
c)	Condition of railings/slab/approach for Bridges		() () () () () () () () () ()
_ d)	Condition of Vent Clearance		5
Observation Remarks:-			3
Not meuntained			A V
	20 mm 20 0 0 1970 N		
			No. 10 and 10 an
3.	Road Furniture		
a)	Whether sign boards/informatory/caustones/Pavement road markings are pre-	ntionary Board/ km & 200m ovided and maintained	V.
Observation Remarks:-			85
Not membaned			27-8 62.
4.	Compliance History		The second secon
a)	Status of ATR's & any others	The same of the sa	
			<u></u>

Overall Rating

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer:- Kymay Rakesh Designature:- grader? v. s.