

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 15/12/2021		District: Aurangabad
Division : Aurangabad		Length (km): 3.065 km
Name of the Road: Deo Kanchampur path to Chapta Mod to Bhatu Bdg		
Scheme/Programme:		MMGSY (SC)
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Road Maintenance Road Maintenance work was going on		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- Maintained		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Road maintenance work was going on		
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Kumar Rakesh
 Designature:-

आरंगबाद नगरपालिका
 (नगर कार्य विभाग)
 कार्य संचाल, पटना

(Signature)