

④ Certificate




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

ESTIMATE FOR EMERGENT REPAIR FOR RESTORATION OF TRAFFIC

FDR (temporary)

Bihar (बिहार) Map



Temporary FDR

Name of the Road :-

Makhdumpur Gulabganj Road Near Dwarika High School (Ikkil)

DISTRICT	:	Jehanabad	
DIVISION	:	Jehanabad	
BLOCK	:	Makhdumpur	
TOTAL COST OF RESTORATION	:	1.009	Lac

Submitted By:
Executive Engineer
RWD WORKS DIVISION
Jehanabad

GENERAL ABSTRACT OF COST

NAME OF ROAD :

Makhdumpur Gulabganj Road Near Dwarika High School (Ikkil)

DISTRICT

Jehanabad

BLOCK

Makhdumpur

DIVISION

Jehanabad

CD STRUCTURES

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)	
RESTORATION COST			
1	Brick Bat Filling	0.448	0.661
2	Hume Pipe 600mm Dia	0.238	0.186
	SUB TOTAL OF Restoration	0.686	0.847
	LABOUR CESS 1% of cost	0.007	0.008
	GST 12 % of cost	0.082	0.102
	SEIGNIORAGE FEE @ 10 % on Minor Mines	0.035	0.052
	TOTAL OF Restoration	0.810	1.009

Pranav K.
 29/08/2021
 RWD

[Signature]
 24/11/21
 RWD

[Signature]
 27.11.2021
 RWD

Technically approved for Rs. 0.81 Lakh
 zero 0.00 Crore 0.00 Lakh
Eighty one thousands 0.00 hundred only

certified copy
[Signature]
 RWD (W) Circle
 Aurangabad

sd—
 S.E.
 RWD (W) Circle
 Aurangabad


BF :- 10.81 Lakh

provisionally sanctioned for Rs. 0.81 lakh

~~Zero~~ Crore Zero lakh Eighty one

~~Zero~~ Hundred Zero only

certified copy



R. RD (A) Circle
Aurangabad

S.E.
R. RD (A) Circle
Aurangabad

बाढ़ क्षतिग्रस्त पथों का अन्तर प्रमंडलीय जाँच प्रतिवेदन हेतु प्रपत्र।

1. निरीक्षी पदाधिकारी का नाम एवं पदनाम :- श्री राजेंद्र प्रसाद, कार्यपालक अभियंता, शा.क.प.नि.
कार्य क्र. 31/बल
2. निरीक्षण की तिथि :- 24/11/24
3. पथ का नाम (शीर्ष के साथ) :- Mukhdumpur Galabganj Road Near Dausika
4. पथ की लम्बाई :- 11.66 k.m
HIGH SCHOOL (EKKIL).
5. कार्य प्रमंडल का नाम :- Jalandhar.
6. प्रखंड का नाम :- Mukhdumpur.
7. पथ की स्थिति :- (पूर्ण / On going) - Out of maintenance.
8. पथ अनुरक्षण अवधि में है :- (Yes/No) नहीं
9. क्षतिग्रस्त भाग की लम्बाई :- 65 M.
10. क्षतिग्रस्त भाग में कराये गये कार्य का विवरणी :-
(लम्बाई x ऊँचाई x गहराई)
 $944 = 35.27 m^3$ (measurement sheet attached)
NP-4, 600mm ϕ , 10.00 M.

11. Temporary Restoration में किस-किस :-
समाग्रियों का उपयोग किया गया है,
उसका विवरणी

Brick, Bats,

Mure pipe, 600 mm ϕ ,

12. अभियुक्ति :-

राजेंद्र प्रसाद
24-11-24

निरीक्षी पदाधिकारी का हस्ताक्षर
पदनाम सहित