

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 17/12/2021		District: Aurangabad	
Division : Aurangabad		Length (km): 8.90 km	
Name of the Road: Sanda to Kutumba (Mali to Baluganj via Kutumba) Road			
Scheme/Programme:		MR	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	S
<b>Observation Remarks:-</b> <p style="text-align: center;">Maintenance work was going on.</p>		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
<b>Observation Remarks:-</b> <p style="text-align: center;">Maintained</p>		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
<b>Observation Remarks:-</b> <p style="text-align: center;">Maintenance work was going on at the time inspection</p>		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Kermar Rakesh  
 Designature:-

(Signature)