

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 15/12/2021		District: Aurangabad	
Division : Aurangabad		Length (km): 4.13 km	
Name of the Road: Deo Balugamji Road to Balthara			
Scheme/Programme:		MMGSY (Gen)	
Sl. No.	Parameters to be checked	Remarks (S/U)	
1.	Pavement		
a)	Condition of Surfacing	S	
b)	Riding Quality	S	
c)	Road Camber	S	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S	
e)	Contraction Joints provided or not (CC Pavement)	S	
f)	Compaction of flank/slope & raincuts if any	S	
Observation Remarks:- Road found maintained properly			
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S	
c)	Condition of railings/slab/approach for Bridges	—	
d)	Condition of Vent Clearance	S	
Observation Remarks:- Maintained			
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S	
Observation Remarks:- overall road maintained satisfactorily.			
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Kumar Rakesh

Designature:-

(Signature)