

## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 14/12/2021		District: Aurangabad
Division : Aurangabad		Length (km): 5.20 km
Name of the Road: Sahay bigha more to Beli Rd Vra Naugraha Lepura manghar		
Scheme/Programme:		NABARD (MR)
Sl. No.	Parameters to be checked	Remarks (S/U)
<b>1.</b>	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Road found maintained properly.		
<b>2.</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:- Maintained		
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Over all road maintained satisfactorily		
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Kumar Rakesh  
Designature:-

वकनोकी सलाहकार  
ग्रामीण कार्य विभाग  
कार्य अंचल, पटना

(Signature)

14.12.21