

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 14/12/2021	District: Aurangabad
Division : Aurangabad	Length (km): 6.37 km
Name of the Road: Raji via Dosma - Bel Barahi	
Scheme/Programme:	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:- Maintenance was going on. Surface almost completed. Other works in progress.

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:- Maintenance work going on. (a) and (d) completed.

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating : Satisfactory (S) / Unsatisfactory (U) U

Name of Officer:- Kumar Rakesh
Designation:- राजनीकी सलाहकार
गोपनीय कार्य विभाग
कार्य विभाग, पुस्ता

Dated 14.12.2021
(Signature)