

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 14/12/2021		District: Aurangabad
Division : Aurangabad		Length (km): 9.30 km
Name of the Road: G.T. Road - Biseni		
Scheme/Programme:		PMGSY-NEA (MR)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- Maintenance work was going on		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:- Maintained		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Maintenance work was going on at the time of visit or inspection.		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:- Kumar Rakesh

Designation:-

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, कटा

(Signature)

[Signature]
14.12.21