

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Cyan Vibhakar*

2 Name of Block/Road :- *pmusy Teen Dagra to Kogeki' Siman*

✓ (A) For Road:

1. Damage Location/Chainage :- *CL 0920 to 1960m many places*
2. Damage Length :- *34.20m*
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- *Brick bats*
  - (ii) Equipment's/Tools being used in Restoration works:- *Tractor*
  - (iii) Procedure taken up in Restoration works:
  - (iv) Restored Length :- *34.20m*

✓ (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

*[Signature]*  
15-1-21

Signature

(Name of Inspection)  
**Executive Engineer**  
**R.W.D. Works Division**  
**Muzaffarpur East-I**

### GENERAL ABSTRACT

Name of Road PMGSY Teen Dagra to Koyeli Siman

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km)

1.960 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	0.602
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	0.602
TOTAL COST OF PROJECT IN LACS =		0.602

By 0.602 lacs

JE  
RWD

AE  
RWD

RWD

Technically approved for Rs. 0.602 lacs (Rupees  
Sixty thousand two hundred only)

S.E.

R.W.D. Muzaffarpur