	<u>F</u>	FIELD INSPECTION REPORT	
Date Of	Inspection: 24/1/21	District: Siwan	
	: Mahrajganj	Length: 0.480 KM	
Name O	of the Road:	उस समिधर टोला	134
Scheme	/Programme :	GITSNY	
Package		Road Id No. :	
	of the Project :	Ongoing/Completed/Under Maintenance	
Work is	a case of :	New Connectivity/Up gradation/ Ma	ntenance
Sl. No.	Par	rameters to be Checked	Remarks
1	Pavement		
a)	Road Junction condition		s/ự
b)	Condition of Surfacing		S/V
c)	Riding Quality		s/yl
d)	Road Camber		S/X
e)	Whether free from defects such as visible cracks, exposed aggregates in		Yes/No
	case of CC pavement.		
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		ş/şki/u
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No		Yes/No
4	Compliance History		
a)	Status of ATR's & any otl	ners	No
(Overall Rating :		14.

Satisfactory (S)	No. of the last of
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

NAME:

DESIGNATION:

ΑE

MANISH KUMAR OJHA (J.E.)