

**FIELD INSPECTION REPORT**

<b>Date Of Inspection :</b> 24/1/21		<b>District:</b> Siwan
<b>Division:</b> Mahrajganj		<b>Length :</b>
<b>Name Of the Road :</b> 4022 से योस्ट रोड		
<b>Scheme/Programme :</b>		G.T.S.N.2
<b>Package No. :</b>		<b>Road Id No. :</b>
<b>Status Of the Project :</b>		Ongoing/Completed/Under Maintenance
<b>Work is a case of :</b>		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
<b>3</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
<b>4</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	No

**Overall Rating :**

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

**NAME :****DESIGNATION :****AE**

  
 24/1/21  
 (Signature)

  
 24/1/21  
 MANISH KUMAR OJHA (J.E.)