

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vihar

2 Name of Block/Road :- Banni Chowk PMSY Road to Dhala Bandh NH-57

(A) For Road: ✓

1. Damage Location/Chainage :- At ch. 0.450 km
2. Damage Length :- 0.012 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.012 km

(B) For Bridge: x

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

CE
RWD WORK DIVISION
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Bunni Chowk PMGSY Road to Dhala Bandh NH-57

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km) 3.290 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.663
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	4.663
TOTAL COST OF PROJECT IN LACS =		4.663

[Signature]
18/11/2020

JE
RWD

[Signature]
18/11/2020

AE
RWD

[Signature]
18/11/2020

EE
RWD

*Technically approved for Rs. 4.66 lacs (Rs. four
lacs sixty six thousand) only*

[Signature]
SE, RWD
Wore's circle
Muzaffarpur