

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan Vibhakar

2. Name of Block/Road - Sahila Sampur - Panchayat under Simri Baland Village
Shivchandra Ram ke Ghar to mukhay path

A. For Road ☒

1. Damage Location/Chainage : 0.350 km, 0.550 km

2. Damage Length : 0.0437 km

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works : brick bats

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length : 0.0437 km

B. For Bridge ☒

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Signature of JE/AE/EE

18/12/20
Signature

(Name of Inspector)

EE

RWD WORK DIVISION
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Sahila Rampur Panchayat Under Simari Basnt Village Shivchandra Ram Ke Ghar to Mukhay Path
District Muzaffarpur
Block Bochaha
Division Muzaffarpur East-2
Length of Road (in Km) 0.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	7.565
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	7.565
TOTAL COST OF PROJECT IN LACS =		7.565

Santosh Kumar
25/11/2020

JE
JE
RWD

AE
AE
RWD

EE
EE
RWD

Technically approved for Rs. 7.57 lacs (Rs. Seven lacs fifty seven thousand) only.

1/11/2020
SE, RWD
Work Circle
Muzaffarpur