

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - Nathuni Sah keghar paschim to Sushil Ray ke
ghar via school tak

A. For Road ✓

1. Damage Location/Chainage : At many point
2. Damage Length : 0.099 km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : brick bats.
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.099 km

B. For Bridge X

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

Signature

(Name of Inspector)

EE
RWD Work Division
muzaffarpur East-2

GENERAL ABSTRACT

Name of Road Construction of Road From Nathuni Sah ke Ghar Pashim to Sushil Ray ke Ghar Via School Tak

District Muzaffarpur

Block Bochaha

Division Muzaffarpur East-2

Length of Road (in Km) 1.558 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
		16.298
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	16.298
	GRAND SUB TOTAL	16.298
TOTAL COST OF PROJECT IN LACS =		16.298

Satish Kumar
15/11/2020

JE
15/11/2020

RWD

AE
15/11/20

AE

RWD

15/11/20

EE

RWD

Technically approved for Rs. 16.30 lacs (Rs. Sixteen lacs thirty thousand) only

SE/RWD
WORKS Circle
Muzaffarpur