

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - Sahila temple panch road to Saidnathrai
- A. For Road ✓ Sunil Choudhary house

1. Damage Location/Chainage : many point
2. Damage Length : 0.0941 km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : brick bats
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.0941 km

B. For Bridge X

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

Signature

(Name of Inspector)

EE
RWD work Division
muzzaffarpur East-I

GENERAL ABSTRACT

Name of Road Sahila Rampur PMGSY Road to Baidhnath ray Sunil Chaudahary House (Link No. -S024)

District Muzaffarpur

Block Bochaha

Division Muzaffarpur East-2

Length of Road (in Km) 1.035 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	10.581
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	10.581
TOTAL COST OF PROJECT IN LACS =		10.581

GA
05/12/2020
JE
RWD

AE
RWD

EE
RWD

Technically approved for Rs 10.581 lac
(Rupees Ten lac fifty eight thousand one
hundred only)

अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर