

17. B. No 822

Schedule XLV-Form No. 134

R. W. D. PAKRIPADAYAR **DIVISION**

~~THE~~
~~PAKRI~~
~~PAKRI~~ **SUB-DIVISION**

MADHUBAN

Ugahya Bazar to Mushar Toli Ugahya Middle School -
via Sakhal Toli Standlak Band

MEASUREMENT BOOK

प्रमाणित किया जाता है कि
माफीपुस्त में मशीन टंकित 100
एक वी पृष्ठ है जिसे श्री तेजनाथ
डोगरा सह आयोगीय कार्य
विभाग कार्य आव प्रमंडल
महोदय के पदनाम से निर्गत
किया गया है

Amr
कार्यपालक कमिश्नर
ग्रामीण कार्य विभाग
कार्य प्रमंडल पकडीदयाल
1.2.20 1.2.20

Sch. XLV—Form No. 134

PAKRIDAYAL DIVISION
MADHUBAN SUB-DIVISION
FETARIA
MADHUBAN

Measurement Book

No.

822

Name of Officer _____

Date of first entry _____

Name of work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

These four lines should be repeated the measurements relating to each work.					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
Name of work - Temporary Restoration					
Work of Road from Warahiya					
Bazar to Mushar Tola Warahiya					
Middle school via shekh Toli					
Grandak Bandh under F.D.R.					
(2245) years 2020-21					
Agency - R.W.D. Works Division Pakhadiya					
Date of work start - 02-09-2020					
Date of work complete - 12-09-2020					
(1) Labour for laying dry					
graded Jhama Khoo					

or stone filler under					
Brick pitching (Brick					
Bats) — as per E/I					
Date — 05-09-2020					
ch — 0.0 to 0.250 km					
$12.40 \times 1.30 \text{ avg} \times 0.450$					$= 7.254 \text{ m}^3$
$4.0 \times 1.90 \text{ avg} \times 1.20$					$= 9.120 \text{ m}^3$
					16.374 m^3
Wageeem					
05-09-2020					
JE					
Verifying Station					
05.09.20					
A E					
(2) Labour for filling sand					
Bag, stitching and					
placing etc —					
as per E/I					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Dated — 08-09-2020					
ch — 0.250 to 0.300 km					
$13.0 \times 2.0 + 1.50 \times 3.0$					$= 83.85 \text{ m}^3$
Dated — 09-09-2020					
ch — 0.300 to 0.330 km					
$8.0 \times 2.0 \text{ avg} \times 1.60$					$= 25.60 \text{ m}^3$
Dated — 12-09-2020					
$16.0 \times 2.0 + 1.50 \times 1.60$					$= 44.80 \text{ m}^3$
					154.25 m^3
1 No sand Bag filled 0.034 m^3 sand					
Hence Nos of Bag $= 154.25 \text{ m}^3$					
					0.034 m^3
					$= 4536.76 \text{ Bags}$
					say 4537 Bags

Waggon

12.09.2020

जि

$\frac{1}{2} \text{ Th}$

12.09.20

A-E

~~12/9/47~~

			JE		Ch Jm
					19.01.20
			X		A-G
			Vijayapuri		
			18/1/20		

**कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, ढाका।**

पत्रांक1798.....

दिनांक26/12/2020.....

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल ढाका।

सेवा में ,

अधीक्षण अभियंता,
ग्रामीण कार्य विभाग,
कार्य अंचल, मोतिहारी।

विषय:— वर्ष 2020 के बाढ़ में क्षतिग्रस्त पथों को मोटरेबुल कराने हेतु किये गये कार्यों की जाँच के संबंध में।


प्रसंग:— मु0अ0-4(मु0)विविध (कार्य)-23-40/2016- 2789 पटना, दिनांक 21.08.2020 एवं भवदीय कार्यालय आदेश ज्ञापांक- 1344 दिनांक 28.08.2020

महाशय


उपर्युक्त विषयक एवं प्रासंगिक पत्र के अनुपालन में कार्य प्रमंडल, पकड़ीदयाल द्वारा उपलब्ध कराये गए मोटरेबुल पथों की सूची में अंकित पथों का अधोहस्ताक्षरी तथा सहायक अभियंता एवं कनीय अभियंता के द्वारा निरीक्षण किया गया। निरीक्षण के दौरान कार्य प्रमंडल, पकड़ीदयाल द्वारा प्रतिवेदित सभी पथों में मोटरेबुल का कार्य कराया गया है एवं वर्तमान में यातायात चालू है।

सादर सूचनार्थ एवं अग्रेतर कार्रवाई हेतु समर्पित।

अनु0- निरीक्षण किये गए पथों की सूची।



26/12/2020

कनीय अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, ढाका।


26/12/2020

सहायक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, ढाका।

विश्वासभाजन,


26/12/2020

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, ढाका।

अधीक्षण अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य अंचल, मोतिहारी


कार्यालय आदेश

कार्यालय आदेश संख्या-

दिनांक.....

विभागीय निर्देशानुसार वर्ष 2020 के बाढ़ एवं अतिवृष्टि से ग्रामीण कार्य विभाग के पथों एवं पुलों में हुई क्षति के कारण आवागमन को सूचारु करने हेतु युद्ध स्तर पर कार्य प्रगंडलों को कार्य कराने का निर्देश प्राप्त है। इस सम्बन्ध में सचिव, ग्रामीण कार्य विभाग, बिहार पटना के निर्देश के आलोक में इन सभी कार्यों की भौतिक सत्यापन हेतु इस कार्य अंचल में पदस्थापित कार्यपालक अभियंताओं के बीच प्रगंडलवार जाँच कार्य हेतु निम्नवत कार्य क्षेत्र आवंटित किया जाता है।


क्रमांक	वर्तमान पदस्थापन कार्य प्रगंडल का नाम	जाँच हेतु आवंटित कार्य प्रगंडल का नाम
1	कार्यपालक अभियंता, मोतिहारी	कार्य प्रगंडल रक्सौल
2	कार्यपालक अभियंता, रक्सौल	कार्य प्रगंडल ढाका
3	कार्यपालक अभियंता, अररराज	कार्य प्रगंडल मोतिहारी
4	कार्यपालक अभियंता, चकिया	कार्य प्रगंडल अररराज
5	कार्यपालक अभियंता, ढाका	कार्य प्रगंडल पकड़ीदयाल
6	कार्यपालक अभियंता, पकड़ीदयाल	कार्य प्रगंडल चकिया


अधीक्षण अभियंता
ग्रामीण कार्य विभाग,
कार्य अंचल, मोतिहारी

ज्ञापक-1344

दिनांक 28/08/2020

प्रतिलिपि- कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रगंडल मोतिहारी/रक्सौल/अररराज/चकिया/ढाका/पकड़ीदयाल को सूचनार्थ एवं आवश्यक कार्रवाई हेतु प्रेषित।


अधीक्षण अभियंता
ग्रामीण कार्य विभाग,
कार्य अंचल, मोतिहारी

SIN	Division	Road Name	Scheme	Road Status	Is Mainline (Y/N)	Is Agreement (Y/N)	Length (km)	Length of Damage Part (km)	Tentative Restoration (in Lacs)	Actual Restoration (in Lacs)	Remarks	PDR Year	Start Latitude	Start Longitude	Mid Latitude	Mid Longitude	End Latitude	End Longitude	Block
41	Pakridyal	Sabli to Narihar Bandh	GTSNY	Completed	Yes	Yes	1	0.25	1.1	0	submerged in water and wash out of soil under the PCC portion.	2020-21	26.482694	85.065601	26.482802	85.076428	26.455088	85.040721	Madhuban
42	Pakridyal	Mushar Toli To Kailhara	MMGSYS CI	Completed	Yes	Yes	2.066	0.47	0.7	0	Carriageway damaged	2020-21	26.415462	85.112074	26.408246	85.117811	26.408032	85.125728	Madhuban
43	Pakridyal	T04 - Sawagla	PMGSY	Completed	Yes	Yes	2.6	0.11	2.2	0	Carriageway and flunk damaged	2020-21	26.42929	85.123972	26.432767	85.109409	26.430371	85.101303	Madhuban
44	Pakridyal	Kauriya - Dubcha	PMGSY	Completed	No	Yes	5.443	0.06	2.2	0	Carriageway damaged	2020-21	26.444515	85.16089	26.441706	85.183074	26.45035	85.196973	Madhuban
45	Pakridyal	Lahri NH-104 - Kauriya-Path	PMGSY- NEA	Completed	No	No	2.75	0.105	3	0	Carriage way damaged	2020-21	26.465693	85.176055	26.465383	85.190224	26.451793	85.195844	Madhuban
46	Pakridyal	Garha Bazar to Mushar Tola Garha Middle School Via Sheeh Toli Gaudak Bandh	MMGSYS CI	Completed	Yes	Yes	1.445	0.55	1.8	0	Carriageway and old HP culvert damaged	2020-21	26.390044	85.127827	26.387121	85.127043	26.382312	85.13024	Madhuban
47	Pakridyal	Madhuban Pokhara To Dhumnagar	MMGSYS CI	Completed	Yes	Yes	2.831	0.08	1.6	0	Ins breach	2020-21	26.561061	85.304138	26.549781	85.218705	26.533965	85.196691	Pachhara
48	Pakridyal	Shekhaura Chowk to Sekhaura Gaoon Via Rupaulia Main Road	MMGSY- NDB/BRIC SH	On Going	No	Yes	1.224	0.035	1.5	0	Breache-Ins	2020-21	26.508343	85.170585	26.50683	85.190017	26.528047	85.183248	Pachhara
49	Pakridyal	Madhuban Meela Bazar Lohargama Road to Maniyarpur Bhagat Tola	MMGSYS CI	On Going	No	Yes	3.535	0.065	5.8	0	crust damaged with 2nos Breaches	2020-21	26.413598	85.143026	26.415642	85.144687	26.432378	85.150689	Madhuban
50	Pakridyal	Phenbura Prakhind Anantgar Rupaulia Panchnayal ke Kumbhar Gaoon ke Mahadadit Basti me Path Nirman Kar	MMGSY Genl	On Going	No	No	2.025	0.18	2.5	0	Carriageway damaged	2020-21	26.495069	85.166569	26.495087	85.165228	26.490909	85.160078	Pachhara
51	Pakridyal	Phenbura main Road To Banargasuni	MMGSY Genl	Completed	Yes	Yes	2.399	0.035	2.5	0	2nos breaches and crust damaged	2020-21	26.51606	85.213646	26.520257	85.212503	26.524412	85.198939	Pachhara
52	Pakridyal	LD-10 Phenbura Jorhara To Gobindhara (VR8)	PMGSY	Completed	No	Yes	1.15	0.03	1.5	0	carriageway damaged	2020-21	26.534707	85.195883	26.536643	85.200453	26.539602	85.206527	Pachhara
53	Pakridyal	Manjhar to Khuswaha Tola	NABARD	Completed	Yes	Yes	2.637	0.1	3	0	submerged in water, crust damaged, flunk damaged	2020-21	26.509052	85.05168	26.51649	85.050545	26.525457	85.07139	Pakri Dayal
54	Pakridyal	Repair of road from Pakridyal to Dicksa road (Part-2)	MR	Completed	Yes	Yes	8.9	0.35	8	0	cillage way damaged at multiple change	2020-21	26.554265	85.063215	26.561934	85.057745	26.627162	85.11447	Pakri Dayal
55	Pakridyal	LD42-T04 Manpur Mal (TRACK4)	PMGSY	Completed	Yes	Yes	2.34	0.035	0.8	0	flunk & carriage way damaged, temporary restoration is in progress	2020-21	26.421785	85.078324	26.432871	85.108942	26.430797	85.118199	Madhuban
56	Pakridyal	Parahi Supargipur Road to Naya Tola	MMGSY- NDB/BRIC SH	On Going	No	Yes	1.11	0.1	3	0	flunk & crust damaged	2020-21	26.569351	85.159952	26.568131	85.158235	26.567128	85.175523	Pachhara
57	Pakridyal	Narayanpur Chowk P.M.G.S.Y Road T02 to Jalsbadpur Naushkar	MMGSYS CI	Completed	Yes	Yes	1.275	0.4	7.5	0	one breach, flunk and crust damaged	2020-21	26.494188	85.243299	26.349187	85.249446	26.421608	85.258179	Pachhara
58	Pakridyal	Konja Kajraha Nona Tola To Madhuban Sheeha Road	GTSNY	Completed	Yes	Yes	0.83	0.062	1.2	0	carriageway damaged	2020-21	26.477332	85.196472	26.455968	85.196535	26.451657	85.196824	Madhuban
59	Pakridyal	Naumraadih to mahauliya	GTSNY	Completed	No	No	1.12	0.16	2.8	0	Ins breach	2020-21	26.470159	85.13148	26.49359	85.134056	26.498455	85.132374	Madhuban

26/12/2020
JE, RUD, Dhaka

26/12/2020
JE, RUD, Dhaka

26/12/2020
JE, RUD, Dhaka

26/12/2020
JE, RUD, Dhaka