Inspection Report for Flood Damage Work

Date:-1 Name of PIUs: - Cyan Vibhakar 2 Name of Block/Road: - Aurai / Lo78 Pracy road hunne house to Jonky
(A) For Road:

Khurd (VR44) 1. Damage Location/Chainage :- Orquotem, o. 600 lm, o. motor 2. Damage Length :- 0.121921m 3. Nature of Damage 4. Details of Restoration Works :-Material being used in Restoration works:- Brick bat (i) Equipment's/Tools being used in Restoration works:- Tractor. (ii) Procedure taken up in Restoration works: (iii) Restored Length (iv) 0.12192100 (B) For Bridge: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: (i) Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

(iii) Procedure taken up in Restoration works:-

Signature

(Name of Inspection) कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

L078 PMGSY Road Nunu House to Jonky Khurd (VR44)

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

1.158 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
and here so	Earthwork	0.000
7	Jhama metal	3.666
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	3.666
OTAL C	DST OF PROJECT IN LACS =	3.666

RWD

AE Moll

gay EE W)

Technically approved for PS 3.666 lac (Rupees three lac stray six thousand six hundred only)

// Josephan अधीक्षण अभियंता

ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर