Inspection Report for Flood Damage Work

Date:

- 1. Prame of PIUs Gyan vibharlend
- 2. Name of Block/Road ALREU / NH-77 Cropalpur to simori chiketa poth
- A. Fer Road
- 1. Damage Location/Chainage

many places

2. Damage Length

: 0.3198 km

3. Nature of Damage

.

- 4. Details of Restoration Works
 - i. Material being used in Restoration works: Bree bush
 - ii. Equipments/Tools being used in Restoration works: Traver
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

: 0.31981cm

- B. For Bridge
- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :
 - i. Material being used in Restoration works:
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

Signature of JE/AE/EE

(Name of Inspector)

GENERAL ABSTRACT

ame of Road

NH-77 Gopapur to Simari Chihuta Path

District

Muzaffarpur

3lock

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

6.600 Km

SI. No.	DESCRIPTION		AMOUNT (LAKHS)
1	Jhama metal		4.52
2	Sand Filling	. 451 a.c	0.000
3	Sand bag		0.000
4	H.P.		0,000
	GRAND SUB TOTAL		4.523
TOTAL	COST OF PROJECT IN LACS =	4.523	

RWD

RWD

Technically approved for RS 4-523 lac

(Rubees Four lac fifty two thousand three

hundred only)

अधीक्षण अभियंता ग्रामीण कार्य विभाग

कार्य अंचल,मूजफ्फरपुर