

FIELD INSPECTION REPORT

Date of Inspection : 17-01-2021		District: East Champaran
Division : Sikharha (Dhalca)		Length (km): 0.470 Km
Name of the Road: PWD Chhorasahan path to Chhorasahan word No - 6,7 Saw tola and Musalmara tola.		
Scheme/Programme:	MAINTENANCE	MM 015Y (SC)
Package No.:		Road Id No.: 31708601368
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	6 S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Gopal.
17-01-2021
(Signature)

NAME: Nand Gopal.
DESIGNATION: AE, RWD Dhalca.