FIELD INSPECTION REPORT

Division: Sikharna (Dhaka) Length (km): 0.517 Name of the Road: There has lane Baswaria path to Lane Baswaria	
Package No.: Road Id No.: 3/708601 Status of the Project: Ongoing/Completed/Under Maintenance	
Package No.: Road Id No.: 3/708601 Status of the Project: Ongoing/Completed/Under Maintenance	
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	THE PROPERTY OF THE PARTY OF TH
Sl. No. Parameters to be checked	Remarks
1. Pavement	estation of the second
a) Road Junction condition	VS/U
b) Condition of Surfacing	S/U
c) Riding Quality	S/U
d) Road Camber	S/U
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f) Contraction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank/slope & raincuts if any	Yes/No
Cross Drainage	Avenue for Money to the
a) Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c) Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Forniture	and the second second second
a) Whether sign boards/informatory/cautionary Board/km & 200 stones/Pavement road markings are provided and maintained	m Yes/No
Compliance History	A STATE OF THE PARTY OF THE PAR
a) Status of ATR's & any others	NO ATA
verall Rating : Satisfactory (S)	16S>

Satisfactory (S)	65,
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 2021

NAME: Mand Ropel.

DESIGNATION: AE, R.W.D. Dhaka.