

FIELD INSPECTION REPORT

Date of Inspection :	03/02/21	District:	NAWADA
Division :	RATAULT	Length (km):	0.600 km
Name of the Road:	Dembur Village to Sirkaha Road		
Scheme/Programme:	MAINTENANCE	Mingalsy	
Package No.:	1050 270/13/3	Road Id No.:	1050270/13/3
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SR)

Unsatisfactory (U)

(Signature)

NAME:

SUMAN-KUMAR

DESIGNATION:

ASSISTANT-ENGINEER