FIELD INSPECTION REPORT

ate of Ir		4/02/2021	District: NAWA1	DA C	
Division: RAJAULI Length (km): O			Length (km): 0 - 900	-900 KM	
lame of	the Road: So	Waiya GOPO	Upur germa to Gopal		
icheme/I	rogramme:	MAINTENANCE	mm (451)		
ackage			Road Id No.: 1050270	130032	
Status of the Project: Ongoing/Completed/Under Maint Work is a case of: New Connectivity/Up gradation/				epi – e gr	
D. W. W. 18. 1	A CASE OF:	1200 1400 1 1 1 1 1 1 1 1 1	Up gradation/ Maintenance		
SU No.		Parameters to	o be checked	Remarks	
1,	Pavement	16. 1 1 1 11 11	i.e		
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
7	Gross Drains	Z et la constant	Andrews of the Commence		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
如軟	Compliance I	listory	4		
a)	Status of ATR	's & any others		12.77	

Overall Rating

_

N/Awork is in imagness

04/02/202/ (Signature)

NAME: SLIMAN - KLIMAR

DESIGNATION: ASCISTANT ENGINEER