## FIELD INSPECTION REPORT

	•					
Date of	Inspection:	4-01-2021	District: Nawada			
Division	sion: Rasyuli Length (km): 2.900 14			r1		
Name o	the Road:	tardia seco	tor AC TO NH-3			
Scheme	Programme:	MAINTENANCE	on-going	1000		
Package	No.:	NIA	Road Id No.: 105027	130085		
Status of the Project: Ongoing/Completed/Under Mainten				A Activity		
Work is a case of:		New Connectivity/Up gradation/ Maintenance				
SI No.		Parameters to	be checked	Remarks		
1.	Pavement	ement				
a)	Road Junction condition			S/U		
b)	Condition of Surfacing			S/U		
c)	Riding Quality			S/U		
d)	Road Camber		S/U			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No		
ŋ	Contraction Jo	on Joints provided or not (CC Pavement)		Yes/No		
g)	Compaction of flank/slope & raincuts if any			Yes/No		
2.	Gross Drainage					
<b>a</b> )	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U			
c)	Condition of railings/slab/approach for Bridges			S/SRI/U		
<b>3</b>	Road Furnitus	re				
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Yes/No		

stones/Pavement road markings are provided and maintained

Overall Rating

a)

Satisfactory (S)	2	$\Box \gamma$
Satisfactory but requires Improvement (SRI)	_	AIN
Unsatisfactory (U)		

NO

NAME:

SHALEN SINHA

Compliance History

Status of ATR's & any others

DESIGNATION: 5.9