

Name to work— 1
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME of WORK: Restoration of Bridge Approach Mingant Sani Road to Bela Govind Path.					
Authority: E-E R.W.D					
Works Division, Dhamdaha.					
1- Supply, fitting and fixing of Bamboo (62 mm to 75 mm) dia					
B x 50 = 400 Miter.					
2- Labour for driving					

(62 mm to 75 mm)					
dia Bamboo piles					
15.0 Miter length = 667 Miter.					
3- Supply, fitting and fixing Bamboo woven chanchay					
50 Miter x 15 Miter = 75 M ² .					
4- Supply and spreading of Brick Bats					
900 Miter. 5.0 M x 3.50 Miter					
x (0.80 + 0.90) M					
2 = 14.8 BM ³					
7 M x 3.50 M x (0.80 + 0.90) M					
= 20.82 M ³					
Continuation T = 35.72 M ³					

B/R 35.74 m³

[illegible]

Scanned by CamScanner

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dhamdaha.

2. Name of Block/Road- Misganj Sassi Road To Bela Kodich Path.
(Bridge Approach)

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 27.00m

3. Nature of Damage :

4. Details of Restoration : side and Top of the surface damage due to flood.

i Material being used in Restoration : Brick Bat.

ii Equipment/Tools being used in Restoration works: Tractor

iii Procedure taken up in Restoration works : Manual

iv Restored Length : 27.00m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Signature of JE/AE/EE

[Signature]
28/1/21

[Signature]
28.01.21

Signature

(Name of Inspector)

[Signature]
28/1/21