

↑

No. and date of agreement.
(These four lines should be repeated at the
commencement of the measurements relating to each
work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME of WORK - Retention of Road 16.57 to Kurnool Taluk No. 01.					
Authority - G. E. R. W. N					
Work Division, Dhamdham Supply and Spreading of Brick Ball					
CH- 5.50 mth.					
14.20M x (2.70 + 3.54) M					
2					
x (0.60 + 0.90 + 1.20 + 0.80)					
4					
238.58					

$12.40 \text{ M} \times \frac{(2.40 + 3.60)}{2} \text{ M}$
 $\times \frac{(1.20 + 1.50 + 0.90)}{3} \text{ M}$
 $= 48.24 \text{ M}^3$
 $9.20 \text{ M} \times \frac{(1.80 + 3.20)}{2} \text{ M}$
 $\times \frac{(1.30 + 1.80 + 1.10)}{3} \text{ M}$
 $= 32.20 \text{ M}^3$
 $T = 119.02 \text{ M}^3$
 Pruman
 29-11-2026
 (J.K)
 day
 30/11/20
 GSE
 29.11.20

Continuation
Executive Engineer,
Rural Works Department
Works Division Dhamdaha (Purnea)

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dhamdaha

2. Name of Block/Road- LO57 to Kulkoon Tolg No-I

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 36.80 m

3. Nature of Damage : Slope damage due to flood.

4. Details of Restoration :

i Material being used in Restoration

: Brick Beefs

ii Equipment/Tools being used in Restoration works:

: Tractor

iii Procedure taken up in Restoration works

: Māmanal

iv Restored Length

: 36.80m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

:

ii Equipment/Tools being used in Restoration works:

:

iii Procedure taken up in Restoration works

:

iv Restored Length

:

P. Kumar
29-01-2021

Signature of JE/AE/EE

[Signature]
29/1/21
EE

[Signature]
29-1-21
EE

[Signature]
29/1/2021

Signature

(Name of Inspector)