

Name of work -
 Situation of work -
 Agency by which work is executed -
 Date of measurement -
 No. and date of agreement
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
Name of the work:-	Restoration				
of traffic From T01 to Nartolia					
charge head - 2245					
Authority:- RWD letter NO- 2789					
dated 21/08/2020 and verbal order					
of EE RWD Nhandaha					
Agency:- Bharat Bhawan					
Date of Entry:- 30/11/2020					

Record Entry

① providing brick bats including spreading laying compacting

$$\begin{array}{l}
 15 \times (2.16 + 3.66) \times (1.9 + 2.10) \\
 \quad \quad \quad 2 \quad \quad \quad + 2.4 + 1.8 \\
 \hline
 = 15m \times 2.91m \times 2.05m = 89.48m^3
 \end{array}$$

$$\begin{array}{l}
 16 \times (2.03 + 3.48) \times (1.7 + 2.00 + 2.0) \\
 \quad \quad \quad 2 \quad \quad \quad 1.70 \\
 \hline
 \end{array}$$

$$\begin{array}{l}
 16m \times 2.75m \times 1.9m = 83.75m^3 \\
 \text{Continuation} \\
 \text{Total} = 172.23m^3
 \end{array}$$

2

Schedule XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

(2) Labour for driving 2 mm to
75 mm dia Bamboo piles
including cutting to in proper
Size and Shapes etc -
 $30 \text{ m} = 100 \text{ m}^2$
0.3

$$\text{Again } 100 \times 4 = 400 \text{ m}$$

$$\text{Required value} = \frac{400}{0.3} = 1333 \text{ m}$$

(3) Supplying fitting and fixing
of bamboo 60 mm to
75 mm dia Runners fixed.

at every vertical pile

with Nails 20 S.W.G. 6.2

wire - do - + do - -

$$\text{Qty} = 8 \times 100 \text{ m} = 800 \text{ m}^2$$

(4) Supplying filling and
fixing in position
split Bamboo woven
charbagh -- do --
-- do - -

$$\text{Qty} = 100 \text{ m} \times 1.5 \text{ m} = 150 \text{ m}^2$$

~~100 m²~~
~~100 m²~~
~~30 ft head~~
~~30 ft head~~
~~30 ft head~~

~~100 m²~~
~~100 m²~~
~~30 ft head~~
~~30 ft head~~
~~30 ft head~~

20.11.20
Executive Engineer
Rural Works Department
Division Dhamdaha (Pune)

Continuation

Date: Inspection Report for flood damage work
1. Name of PIs - Dhamdaha

2. Name of Block/Road - Barahara Kotli / P.O. to Nartolia

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 31.0 M

3. Nature of Damage : Side cutting due to flood

4. Details of Restoration :

i Material being used in Restoration : Bamboo, Brick bats

ii Equipment/Tools being used in Restoration works: Tractor

iii Procedure taken up in Restoration works : Manual

iv Restored Length : 31.0 M

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Signature of JE/AE/EE

J-E
AT

28/01/2021
EV

Signature

(Name of Inspector)

Ombar
28/01/2021

SABU
28/01/2021
J-E