

Name of work
 Situation of work
 Agency by which work is executed
 Date of measurement
 No. and date of agreement
 (These four lines should be repeated at the commencement of the measurements relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Restoration of traffic from Hanuman Nagar Chakla to Bhatara					
Charge head - 2245					
Authority - R.W.D. letter no - 2789 dated - 21/08/2020 and verbal order of EE RWD Dhamdaha					
Agency - padma Construction					
Date of entry:-					

① providing brick bats including spreading, leveling, compacting.					
$1 \times 17.0 \times (5.98 + 9.06) \times (2.9 + 3.7 + 4.50 + 2.3 + 2.0)$					
= 393.75 m ³					
Executive Engineer, Rural Works Department, Works Division Dhamdaha (RWD)					

Continuation

Inspection Report for flood damage work

Date:

1. Name of PIUs- *Dhandaha*

2. Name of Block/Road- *Bhatara Kotli/Hanuman Nagar chakla to Bhatara Road*

A. For Road

1. Damage Location/Chainage :

2. Damage Length : *17.00 M*

3. Nature of Damage : *washout due to flood*

4. Details of Restoration :

i Material being used in Restoration : *bricks bats, Bamboo*

ii Equipment/Tools being used in Restoration works: *Tractor*

iii Procedure taken up in Restoration works : *Manual*

iv Restored Length : *17.00 M*

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Signature of JE/AE/EE

[Signature]
28/1/21
AD

[Signature]
28.01-21
EE

Signature

(Name of Inspector)

[Signature]
28/1/2021

[Signature]
28/01/2021
J.E.