

FIELD INSPECTION REPORT

Date of Inspection :

Division : Sikharha (Dhaka)

District: East chombaron

Name of the Road: Dhaka Ghorashan Path Bhaserwa to Digla Bhaserwa

Length (km): 0.790 km

Scheme/Programme: MAINTENANCE

MMGSY(CSC)

Package No.:

Road Id No.: 31708601331

Status of the Project:

Ongoing/Completed/Under Maintenance

Work is a case of:

New Connectivity/Up gradation/ Maintenance

Dakshin
tola ward-21

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

N.A.

Overall Rating :

Satisfactory (S)	<u>S</u>
Satisfactory but requires Improvement (SRI)	<u>—</u>
Unsatisfactory (U)	<u>—</u>

Gopal
17/01/2021
(Signature)

NAME: Nand Gopal

DESIGNATION: AE, R.W.D. Dhaka.