FIELD INSPECTION REPORT

200		TIELD INSPE	<u>CTION REPORT</u>	
Date o	f Inspection:	81/2021	District: No Associate	
Divisio	m: Redal -		Hayamala	
Name	of the Ronds C	Kanaha Gapy	Length (km): 2.695 km	
		MAINTIENANCE	Ke Pranon Pavidas M	10x to from
Packag	c No.:	T. T	Road Id No.:	unsper to
Status of the Project: Onuning/Complete. // In A. A.				
Work i	s a case of:	New Connectivity/U	p gradation/ Maintenance	
SI. No.	Parameters to be checked			Remarks
1.	Pavement			Kemarks
a)	Road Junction condition S/U			
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3. ,	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance His	tory		
a) :	Status of ATR's	& any others		187
			1	

Overall Rating

Satisfactory (S)	NIA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 18.1.2021

NAME:

DESIGNATION: