

4 Details of Restroration Works:

iv Restored Length:

i. Material being used in Restoration Works:


iii Procedure taken up in Restoration Works:

ii Equipments / Tools being used in Restoration Works:

(7)
Inspection Report For Flood Damage Work
Date: 1 Name of PIUs: Capalgani, 2.
2 Name of Block/Road: Bai kentheur Kottours Bayer Pwo To Novings Tolg A For Road Knit perce Basen p. W.D To Novinger Tola
A For Road Knitpurce Bosson P.W.D To Norwiger Tola
1 Damage Location / Chainage: 0 9 to 7/5 m
2 Damage Length: 173 m
3 Nature of Damage: Heavy Rain / Flood
4 Details of Restroration Works:
i. Material being used in Restoration Works: Brick Bats
ii Equipments / Tools being used in Restoration Works: JCB, Treeter, Irol; Beleky, Roller
iii Procedure taken up in Restoration Works:
iv Restored Length: 173 m
B For Bridge N/A
1 Damage Location / Chainage:
2 Damage Length:
3 Nature of Damage:

(尼斯尼伊斯曼尼亚河eer R.W.D. W.D.

Hathua







गामीण कार्त विभाग

Rural Works Department, Govt. of Bihar

FLOOD DAMAGED REPAIR (F.D.R.)

STATE :- BIHAR

DISTRICT :- GOPALGANJ

BLOCK :- BAIKUNTHPUR

Krtpura Bazar PWD To Noniya Tola

ESTIMATED COST - RS.

1495500.00

SUBMITTED BY :-EXECUTIVE ENGINEER

RWD (W) DIVISION GOPALGANJ-2

Report

Name of Work

:- Motorable work of Krtpura Bazar PWD To

Noniya Tola

Estimated Cost

:- 1495500.00

Total length of Road

:- 0.715 km

Description :- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road. Hence there has been a provision of laying 1 Nos of R.C.C. NP3 1000 MM Dia hume pipe.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

191913030 J.E.

A.E.

F.F. 7

ailed Estimate For Motorable Work in Road from PMGSY Path To Mangal Rai Ke Tola damaged due to Heavy rain/flood for year 2020-2021

Items	No.	L (M.)	W (M.)	D (M.)	Qty.	Unit	Rate	Amount
Providing brick bats billed in ditches including all cost of labour & material with all complete job.		ନ୍ତ କମଧ୍ୟ ମଧ୍ୟ କମିତି	na Supre	nneguz isi Chilif				
CH - 0 M to 715 M	1	11.00	3.00	1.50	49.50	М3		
	1	10.00	1.20	1.50	18.00	М3		
2020	1	16.00	3.00	1.20	57.60	МЗ		
	1	6.00	3.00	1.60	28.80	M3		
	1	14.00	2.50	1.20	42.00	М3		
	1	2.00	2.10	1.25	5.25	М3		
	1	18.00	2.00	1.40	50.40	М3		
	1	3.00	1.50	1.36	6.12	М3		
30	1	5.00	2.50	2.00	25.00	М3		
78.	1	8.00	2.00	2.00	32.00	М3		
	1	10.00	2.00	1.50	30.00	МЗ		
	1	15.00	3.00	1.20	54.00	М3		
	1	20.00	3.00	1.80	108.00	М3		
	1	2.00	2.00	1.45	5.80	М3		
	1	4.00	1.00	1.40	5.60	МЗ		
	1	9.00	1.30	1.50	17.55	М3		
	1	10.00	1.45	1.50	21.75	М3		
0	1	10.00	2.50	2.00	50.00	МЗ		
Less for H.P.	0.79	1.23	1.23	5.00	5.98	М3	2412-11	1450619:
Less for the v					601.39		2427.6 5	<u>1459974.2</u> 5
Providing & laying 1000 MM Dia NP3 Hume Pipe in single	2	2.50			5.00	М	2744750 4159:56	13723 ~ 20797.8 0 1464342~
row -do-do- complete job.								1480772.05
						+		14807.72
Add 1 % Contigency							Total	1495579.77
				+			Say	1495500.00
							n)	1438900-

1495500.00 Ph 1478 9852 Say Ps 14.740 h E.E.

Zeventy Mine Thousand) and 21/01/2) Superintending Engineer RWD Works Circle, Siwan har lell as ALL TERMS 12 60 V Mark Phys. C. Program The Physics 1.6.20音振设 THE WAR