

# FIELD INSPECTION REPORT

|   |  |
|---|--|
| Date of Inspection : 5.2.21                                       | District: Namtal   |
| Division : Regular  | Length (km): 0.210   |
| Name of the Road: Laxmanra Pharyangra Bazar to Rasalpa Bazar 70/6 |  |
| Scheme/Programme: MAINTENANCE                                     |  |
| Package No.:  | Road Id No.: 10502701827   |
| Status of the Project:  | Ongoing/Completed/Under Maintenance  |
| Work is a case of:  | <input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance |

GTSR

| Sl. No. | Parameters to be checked   | Remarks    |
|---------|--|------------|
| 1.      | <b>Pavement</b>  |            |
| a)      | Road Junction condition  | S/U        |
| b)      | Condition of Surfacing   | S/U        |
| c)      | Riding Quality   | S/U        |
| d)      | Road Camber  | S/U        |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No     |
| f)      | Contraction Joints provided or not (CC Pavement)   | Yes/No     |
| g)      | Compaction of flank/slope & rineuts if any   | Yes/No     |
| 2.      | <b>Gross Drainage</b>  |            |
| a)      | Condition of head walls in Hume pipe culverts including its painting   | S/SRI/U    |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts   | S/SRI/U NA |
| c)      | Condition of railings/slab/approach for Bridges  | S/SRI/U NA |
| 3.      | <b>Road Furniture</b>  |            |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No     |
| 4.      | <b>Compliance History</b>  |            |
| a)      | Status of ATR's & any others   | NA         |

Overall Rating :

|   |   |
|---|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

V P 9  
5/2/21  
(Signature)

NAME:

Vinay Kumar

DESIGNATION:

RS